Page 1

October 19, 2009 10:37:37 AM

Item ID:

D3172-041

C **Revision ID:**

Item Name:

Basket Base Assembly

Start Date:

10/19/09

Start Qty: 1.00

Required Date: 10/27/09

Operation

Description



Accept

Setup Start

Stop



Reg'd Qty: 1.00

Reference:

Approvals:

Process Plan:

Date 09-10-19

Tooling:

Date:

Cust Item ID:

Customer:

Draw

Number

Run

Start Stop

QC:

Date:

SPC(Y/N):

Set Up/

Run Hours

Date:

Draw

Rev.

Plan

Code

Accept

Qty

Reject Qty

Reject Insp. Number Stamp

Draw Nbr

Sequence ID/

Work Center ID

Revision Nbr

D3172 Rev C

100

Large Fab

Large Fab Large Fab

Memo

0.00

0.00

1-Cut Qty 4 D3166-1 as per Dwg D3172112-Cut 3/4" x 3/4" square tubing as per

Dwg D3172□3-Drill holes in D3172-3 as per Dwg D3172 □4-Deburr & Remove all markings from material 15-Weld as per Dwg D3172 using Welding

Table and corner Jig & D3172T1 Deburr as r

110

QC

Quality Control

QC9- Inspect visual per QSI004- Fusion Welds

0.00

Memo

QC6- Inspect dimensions to drawing

0.00

//LO71103

120

Memo

Quality Control

Work Order ID 52892

October 19, 2009 10:37:37 AM

Item ID:

D3172-041

Revision ID: C

Item Name:

Basket Base Assembly

Start Date:

10/19/09

Start Qty: 1.00

Required Date: 10/27/09

Req'd Qty: 1.00



Accept

Setup Start

Stop

Cust Item ID: Customer:

Reference:

Approvals:

Process Plan:

Date:

Date:

Tooling: SPC (Y/N):

0.00

0.00

Date:

Draw

Rev.

Plan

Code

Date:

Run Start

Stop



Number Stamp

Insp.

Reject

Sequence ID/ **Work Center ID**

130

Powdercoat

Powder Coating

Operation Description

White Gloss(Ref:4,3.5.1) per QSI005 4.3-Alum

Set Up/ **Run Hours**

09/1/05

Draw

Number

Qty

Accept

Reject

Oty

Memo

1ST COAT: 7:45AM OVEN TEMPERATURE: 3269-FINISH TIME: 5:15 Av

******** 2nd coat if necessary ***************

2ND COAT:

START TIME: 8:30A~

OVEN TEMPERATURE: 209 FINISH TIME: 91000

Quality Control

140

QC3- Inspect Part Finish

0.00

WD 89/11/05

Memo

Work Order ID 52892

October 19, 2009 10:37:37 AM

C



Page 3

Item ID:

D3172-041

Accept

Setup Start



Revision ID:

Item Name:

Required Date: 10/27/09

Basket Base Assembly

Stop

Start Date:

10/19/09

Start Qty: 1.00 **Reg'd Qty:** 1.00

Operation

Description

Cust Item ID: Customer:

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Draw

Number

Run

Start

Stop

Date:

SPC (Y/N):

Date:

Draw

Rev.

Accept

Qty

Reject

Sequence ID/ **Work Center ID**

150

Packaging

Memo

Identify as per dwg & Stock Location:

Run Hours

Set Up/

0.00

Qty

Reject Number

Insp. Stamp

Packaging

Memo

0.00

Plan

Code

160

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

MF 09-11-10

Picklist Print

October 19, 2009 10:37:45 AM

Work Order ID: 52892

Parent Item:

D3172-041RevC

Parent Item Name: Basket Base Assembly

Manufactured

Comments:



Start Date: 10/19/09

Required Date: 10/27/09

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D2012-117RevC		Manufactured	No			100	Each	28.0000	2.0000		-	

Clevis

Warehouse	Lo	c Oty	Loc Code		
Location					
Main Warehouse					
ST		28			
31101		2			
52498		26			PD 09.10.28
	100	Each	9.0000	2.0000	

Basket Hinge

D2232-3RevC

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
ST	8		
50024	2		
51870	6		PD D9.11.02
Main Warehouse			
WA	1		
50986	1	4	1000

October 19, 2009 10:37:45 AM

Work Order ID: 52892

Parent Item:

D3172-041RevC

Parent Item Name: Basket Base Assembly

Manufactured

Comments:



Start Date: 10/19/09

Required Date: 10/27/09

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued		Date Issued	-	Statu	18
D2327-3RevD	-	Manufactured	No			100	Each	46.0000	2.0000		• ,				-

Spacer Bushing

Warehouse Location	Loc	e Oty	Loc Code		
Main Warehouse					
ST		46			
44274		27			8D 09.11.02
44365		9			
51126		10			
	100	Each	74.0000	2.0000	

D2581RevA1

Mounting Bracket

<u>Warehouse</u>	Loc Oty	Loc Code	
Location			
Main Warehouse			
ST	13		
46086	2		
48428	1		
51120	10		-
Main Warehouse			
WA	61		
50872	12		
51745	49		D 09.

October 19, 2009 10:37:45 AM

Work Order ID: 52892

Parent Item:

D3172-041RevC

Parent Item Name: Basket Base Assembly

Manufactured

Comments:



Start Date: 10/19/09

Required Date: 10/27/09

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3166-1RevA1		Manufactured	No		,	100	Each	18.0000	4.0000			

Basket Hoop

Warehouse	Loc	: Oty	Loc Code		
Location					
Main Warehouse					
WA		18			
51248		7			
51951		11			4 90 09.10.26
	100	Each	20.0000	8.0000	

Mounting Lug

D3174-1RevA1

Warehouse	Loc Qty	Loc Code
Location		
Main Warehouse		
ST	20	
41632	20	

PD 09.11.02

October 19, 2009 10:37:45 AM

Work Order ID: 52892

Parent Item:

D3172-041RevC

Parent Item Name: Basket Base Assembly

Comments:



No

Start Date: 10/19/09

Required Date: 10/27/09

Start Qty: 1.00

Required Qty: 1.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
M304EX0.75-16F		Purchased	No			100	sf	201.0648	48.0000			

Expanded Metal Flat SS

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse			
MAT	201.0648065		
110134	6.7		
111630	9.15		
111956	0.000017		
112147	8.29428947		
112311	28.9205		10 09.11.02
112707	148		
	100 f	561.0601 53.6842	
			,

Purchased

304 SQ Tube .75x.75x.065W

Warehouse Location	Loc Oty	Loc Code	
Main Warehouse			
WA	561.0601		
112398	561.0601		 09 10.23





